ECO ECR 44	13 6 JAN 95	REQUESTED BY ECR 788	PREMIER OF 1
REASON FOR CHANGE	DOCUMENTS EFFECTED B64-13020	D SYSTEM BLEED AIR ECU ASSY/INSTL	MATL DISPOSITION
DRAWING ERROR		ASSY/INSTL SERIAL NO EFF	REWORK STORE MFG.
MARKED PRINTS ATTACHED YES \( \bigcup  \text{NO}		OF WITH HOLD	SCRAP USE AS IS
DISPOSITION/COMMENTS		THIS IS AN U	JNINCORPORATED
REV. "IS" C		ECO (STC SH	
		(010 011	0443 <b>5</b> W /
DESCRIPTION 1.0			
SHEET 1A			
"CHANGED" PARTS L	IST ZONE 3C		
"WAS" 3 18276-200 CLAMP AERODUCT "IS" 2 24540-200 CLAMP AERODUCT			
"ADDED" TO PART LIST ZONE 8A UNDER -01 QTY. PER			
1 24302 200	CLAMP AERODUC	. [	
SHEET 2			
"CHANGED" CALLOUT	ZONE 8C		
"WAS" 18276-2	200 CLAMP, 2 P		
"IS" 24540-2 "CHANGED" CALLOUT		L	
"WAS" 18276-2 "IS" 24502-2		89-200C RING	SEAL
"IS" 24502-200 CLAMP, 17189-200C RING SEAL			
	<u>.</u>		
IMPACT YES N INTERCHANGEABILITY □	10 PROCUREMENT ACTION	PRIORITY CH	ANGE CLASSIFICATION  RECORD
DRAWING CHANGE   SPECIFICATION	YES NO □		A MAJOR 🗆 TSO MAJOR
SPARES	DJECT ENG DATE	QAY DA	A MINOR □ TSO MINOR TE FAA SUBMITTAL
R. MADARIS 01/05/95		Cray State 11	4/95 YES
CHECKED BY DATE MFG	DATE	PROD/SPRT DA	
Redikula 05,4495 -			W. Harmaher 1/6/95